

SSM 50348 - 2020-2022 Explorer/Aviator - Illuminated Malfunction Indicator Lamp (MIL) With DTC P04F0, P008A, P0451, P0455, P0456, P0496 And/Or P018C

Some 2020-2022 Explorer/Aviator vehicles may exhibit an illuminated MIL with multiple diagnostic trouble codes (DTC). These DTCs may include P04F0, P008A, P0451, P0455, P0456, P0496 and/or P018C. This may be due to the wiring harness connection at connector C1198. Prior to replacement of any components, inspect the connector and wiring harness for any damage or pin fit concerns. If any damage or pin fit concerns are found, repair the connector or harness as necessary. If no damage or pin fit concerns are found, refer to normal diagnostics.

APPLICABLE VEHICLES

2020 - 2022 CAR: TU U611A AVIATOR

2020 - 2022 CAR: TW U625N EXPLORER