

## **SSM 50411 - 2022 Maverick – Radio Intermittently Does Not Change Stations - Built On Or Before 29-Nov-2021**

Some 2022 Maverick vehicles built on or before 29-Nov-2021 may exhibit a radio intermittently not changing stations. This may be due to the software in the radio. To correct this condition, reprogram the audio front control module (ACM) using the latest software level of the Ford Diagnosis and Repair System (FDRS). For claiming, use causal part 18806 and applicable labor times from Section 10 of the Service Labor Time Standards (SLTS) Manual.

APPLICABLE VEHICLES  
2022 CAR: FE P758N C-PICKUP