

SSM 50435 - 2020-2022 Explorer/Aviator - Driveshaft Vibration - Updated Workshop Manual Diagnostics

Some 2020-2022 Explorer/Aviator vehicles may exhibit a driveline vibration. Workshop Manual (WSM) Pinpoint Tests G (driveline shudder) and H (driveline vibration) have been updated in WSM, Section 205-01.

APPLICABLE VEHICLES

2020 - 2022 CAR: TV U611N AVIATOR
2020 - 2022 CAR: TV U611N AVIATOR
2020 - 2022 CAR: TW U625N EXPLORER
2020 - 2022 CAR: TW U625N EXPLORER