

SSM 50477 - 2021-2022 Bronco - Short Drop Window Feature - Contact With Weather Strip When Opening

Some 2021-2022 Bronco vehicles may exhibit a side door window that gets hung upon the upper door weatherstrip when opening the door causing resistance to opening. This may be due to an incorrect alignment of the side door and/or window. To correct this condition, ensure no damage exists to the door, latch or related components and make necessary repairs before continuing. If concern persists, perform the Up/Down, Fore/Aft Adjustment (steps 1-15), refer to Workshop Manual (WSM), Section 501-11, Front/Rear Door Window Glass Adjustment Procedure. If the concern has not been resolved, perform Pinpoint Test K located in Section 501-11 of the WSM.

APPLICABLE VEHICLES

2021 - 2022 TRUCK: G1 U725N BRONCO