

SSM 50704 - 2022 Explorer/Aviator - Intermittent Passenger Massage Seat Function

Some 2022 Explorer/Aviator vehicles may exhibit an intermittent passenger seat massage function with no diagnostic trouble codes (DTCs). This may be due to the configuration of the seat control module G (SCMG) and seat control module H (SCMH) modules. To correct the condition, reprogram the SCMG and SCMH and run the SCMG and SCMH configuration application with the latest software level of the Ford Diagnosis and Repair System (FDRS). For claiming, use causal part 14F548 and applicable labor times found in Section 10 of the Service Labor Time Standards (SLTS) Manual.

APPLICABLE VEHICLES

2022 CAR: TV U611N AVIATOR

2022 CAR: TW U625N EXPLORER