

SSM 50718 - 2017-2022 F-Super Duty - Pull / Drift During Braking - Workshop Manual Update

Some 2017-2022 F-Super Duty vehicles may exhibit a pull / drift condition during braking. This may be due to the brake pads needing to be broken in. The Workshop Manual, Section 206-00 Symptom Chart for vehicle pulls or drifts during braking has been updated to reflect this information.

APPLICABLE VEHICLES

2017 - 2021 TRUCK: FE P558N SUPER DUTY

2022 TRUCK: FE P558N SUPER DUTY