

## **SSM 50754 - 2022 Maverick - Front Door(s) Can Not Be Unlocked Using The Passive Entry Feature**

Some 2022 Maverick vehicles may exhibit a condition where the front door(s) cannot be unlocked using the intelligent access (passive entry feature). To correct this condition, disable and re-enable the passive entry feature using the information display controls on the steering wheel or HMI screen (if equipped). Select vehicle lock settings/disable and re-enable intelligent access feature. If the functionality of the passive entry feature is not recovered, proceed to perform normal diagnosis. Refer to the Workshop Manual (WSM), Section 501-14 > Handles, Locks, Latches and Entry Systems > pinpoint test R.

APPLICABLE VEHICLES  
2022 CAR: FE P758N C-PICKUP