

SSM 50777 - 2021-2022 Bronco Sport - 1.5L - A/C Compressor Coolant Stains

Some 2021-2022 Bronco Sport vehicles equipped with a 1.5L engine may exhibit coolant stains on the A/C compressor. If coolant stains are observed on the A/C compressor, inspect the A/C system for leaks. Refer to the Workshop Manual, Section 412-00 Climate Control System > General Information > A/C Compressor Leak Detection to ensure proper function. If no performance issues are identified, do not replace the A/C compressor for this condition.

APPLICABLE VEHICLES

2021 - 2022 CAR: HD CX430N C-SUV