

SSM 50789 - 2021 F-150, 2022 F-Super Duty - U0140:00 Stored In The TRM After A Software Update

Some 2021 F-150 and 2022 F-Super Duty vehicles may exhibit diagnostic trouble code (DTC) U0140:82 stored in the trailer module (TRM) after completing a TRM software update. This may be due to software parameters in the gateway module (GWM). This DTC does not affect vehicle function or durability and no additional diagnosis or service is required for this condition at this time. Inform customers that they can continue to drive the vehicle and engineering is currently working on a solution for this condition. Replacement and/or reprogramming of the TRM or GWM will not resolve this condition. Monitor OASIS for additional information and schedule service appointments for customers once the repair becomes available.

APPLICABLE VEHICLES

2021 TRUCK: FD P702N F150

2022 TRUCK: FE P558N SUPER DUTY