

---

**SSM 51011 Various Vehicles - 8F35 - Transmission Slip On  
Acceleration From A Stop When Hot Less Than 5,000 Miles (8,000  
Km) - Built On Or Before 16-Mar-2022**

---

Some 2018-2022 Ford and Lincoln vehicles equipped with the 8F35 transmission built on or before 16-Mar-2022 may exhibit transmission slip during acceleration from a stop when hot. This may be due damaged internal case half pump seals (7N265). To correct the condition, remove the transmission and replace the internal case half pump seals. Refer to Workshop Manual (WSM), Section 307-01.