
SSM 51043 2021-2022 F-150 3.5L PowerBoost, 2022 F-150 Lightning and 2022 Expedition/Navigator - Illuminated ABS Indicator, Stability-Traction Control Indicator And DTC C1013:09

Some 2021-2022 F-150 3.5L PowerBoost, 2022 F-150 Lightning and 2022 Expedition/Navigator vehicles may exhibit an illuminated anti-lock brake system (ABS) indicator and stability-traction control indicator and diagnostic trouble code (DTC) C1013:09 stored in the ABS module. This may be due to ABS module software parameters. This condition does not affect brake system hydraulic functionality. Clear the DTC to restore ABS functionality. Inform customers that engineering is currently working on a solution for this condition and will be released via an over the air (OTA) software update expected in November 2022. Software will update automatically if the vehicle is connected to FordPass/LincolnWay. Monitor OASIS for additional information. Schedule a service appointment for customers that are not connected to FordPass/LincolnWay once the repair becomes available.