
SSM 51146 2021-2022 Mustang Mach-E - Unable To Be Charged With The Mobile Charger

Some 2021-2022 Mustang Mach-E vehicles may exhibit a concern where the vehicle is unable to be charged with the mobile charger. This may be due to a broken charge handle latch. To correct the condition, replace the mobile charger. For claiming, use causal part 10B706 and applicable labor operations in Section 10 of the Service Labor Time Standards (SLTS) Manual.