

SSM 51209

2020-2021 F53/F59 Stripped Chassis - Illuminated ABS Warning Indicator With DTC C0037

Some 2020-2021 F53/F59 Stripped Chassis vehicles may experience an illuminated anti-lock brake system (ABS) warning indicator with diagnostic trouble code (DTC) C0037. If normal diagnostics lead to replacement of the tone ring, be advised that the tone ring has been superseded with improved parts for both the passive (MU9Z-2C026-D) and active (MU9Z-2C026-C) systems. Follow Workshop Manual Section 206-04 for tone ring replacement.