

SSM 51290

2022 Transit - Halogen Lamps Assembly - Turn Signal Indicator Fast Flashing In The IPC With DTC B123A And/Or B123B - Built On Or Before 01-Sep-2022

Some 2022 Transit vehicles built on or before 01-Sep-2022 with halogen lamp assemblies may exhibit a turn signal indicator fast flashing in the instrument cluster panel (IPC) with diagnostic trouble code(s) (DTC) B123A and/or B123B stored in the body control module (BCM). This may be due to a front turn signal lamp socket being internally damaged. To correct this condition, replace the affected front turn lamp socket before replacing the BCM.