

SSM 51291

2013-2019 Police Interceptor Utility - Equipped With Spotlights - Left And/Or Right Windshield Applique/Moulding Replacement

Some 2013-2019 Police Interceptor Utility vehicles, equipped with spotlights, require left and/or right windshield applique/moulding modification if these parts are replaced. Spotlight mounting holes are not present on new replacement windshield appliques/moldings and must be cut using a rotary tool or equivalent. Left and/or right windshield applique/moulding spotlight mounting hole templates are available on the Professional Technician Society (PTS) at Service Tips/Technical Communications and can be printed on an 11X17 inch sheet of paper. Refer to Workshop Manual, Section 501-08 for windshield applique/moulding replacement procedures.