

SSM 51346

2022-2023 Expedition - Liftgate Spoiler Contacting Roof In Freezing Temperatures

Some 2022-2023 Expedition vehicles may exhibit the liftgate spoiler contacting the roof during freezing temperatures when ice is present. Engineering is currently investigating this concern. To correct the condition, repair the spoiler and roof per Workshop Manual, Section 501-03/501-28. For claiming, use causal part 7844210.