

## **SSM 51477**

### **2023 F-Super Duty - DTC U3000:41 Setting In The Audio Control Module (ACM) When A Diagnostic Self Test Is Performed**

Some 2023 F-Super Duty vehicles may experience diagnostic trouble code (DTC) U3000:41 in the ACM when a diagnostic self-test is performed. This may be due to an ACM software error. Replacement or reprogramming of the ACM may not resolve this condition. Inform customers that engineering is currently working on a solution for this condition and will be released via an over the air (OTA) software update expected in Q2 2023. It is recommended that customers that have experienced this concern should verify automatic updates are enabled and that the vehicle has been run long enough to receive updates via OTA. Monitor OASIS for additional information.