

## **SSM 51758**

### **Some 2021 F-150 Vehicles Equipped With A 3.0L Diesel May Exhibit An Oil Change Minder In The IPC Staying At 100%**

Some 2021 F-150 vehicles equipped with a 3.0L Diesel may exhibit an oil change minder in the IPC staying at 100%. This may be due to the software in the IPC. Engineering is currently investigating this concern. Inform the customer they can continue to drive the vehicle. Monitor OASIS for additional updates.