

SSM 51898 2024 Mustang - DTC U3000:49 Setting In The Driver Seat Module (DSM)

Some 2024 Mustang vehicles may exhibit a diagnostic trouble code (DTC) U3000:49 in the DSM with no symptoms present. This may be due to the DSM software. Replacement of the DSM will not resolve this concern. DTC U3000:49 can be cleared and ignored if the power seat functions are working properly and no other DTCs are present in the DSM. Engineering is currently working on a solution and software update is expected in Q1 2024. Continue to monitor OASIS for additional information.