SSM 51929 2023 F-Super Duty - DTC C006A:00 Setting In The TCU When A Diagnostic Self Test Is Performed

Some 2023 F-Super Duty vehicles may exhibit diagnostic trouble code (DTC) C006A:00 in the telematics control unit module (TCU). If this is a stand alone DTC and no other codes are present, this may be due to a TCU software concern. To correct the condition, reprogram the TCU using the latest software level of the Ford Diagnosis and Repair System (FDRS) located under the SW Updates tab. For claiming, use causal part 14G229 and applicable labor operations in Section 10 of the Service Labor Time Standards (SLTS) Manual.