

SSM
46387

Some 2017 F-Super Duty vehicles equipped with BLIS that have had the pickup box removed for upfitter modification may exhibit a BLIS warning message in the message center. To correct this concern, use Integrated Diagnostic System (IDS) service tool version 104.01 or later to configure the BLIS system. These settings can be found under toolbox > module programming > programmable parameters > warning lamps and chimes and must be adjusted in multiple modules. Details can be found on the truck body builder advisory service (BBAS) website, found by clicking the link at the bottom of the webpage at <https://www.fleet.ford.com>. Once at BBAS website, click on bulletins, and refer to published qualified vehicle modifier (QVM) bulletin for BLIS warning programming. Changes to BLIS setup as a result of upfitter modifications are non-warrantable.