

NUMBER: 05-005-15 REV. A

GROUP: Brakes

DATE: November 13, 2015

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

THIS BULLETIN SUPERSEDES SERVICE BULLETIN 05-005-15, DATED JUNE 20, 2015, WHICH SHOULD BE REMOVED FROM YOUR FILES. ALL REVISIONS ARE HIGHLIGHTED WITH **ASTERISKS** AND INCLUDE ADDITION OF BRAKE PACKAGE SALES CODE BRD.

SUBJECT:

Front Brake Squeak/Squeal Noise

OVERVIEW:

This bulletin involves replacing the front brake pads and related hardware.

MODELS:

2014 - 2015 (VF)

Ram Pro Master

NOTE: **This bulletin applies to vehicles within the following markets/countries: NAFTA**

NOTE: This bulletin applies to vehicles built on or before April 8, 2015 (MDH 0408XX) equipped with Anti-Lock 4-Wheel Disc HD Brakes (sales code BR6).

NOTE: **This bulletin applies to vehicles built on or before June 9, 2015 (MDH 0609XX) equipped with 4-Wheel Anti-Lock Disc Power Brakes (sales code BRD).**

SYMPTOM/CONDITION:

The customer may describe a front brake squeak/squeal noise when applying the brakes.

DIAGNOSIS:

If the customer describes the symptom, perform the Repair Procedure.

PARTS REQUIRED:

Qty.	Part No.	Description
1 (AR)	68230105AC	PAD KIT, Front Disc Brake, Includes Hardware ONLY Sales Code BR6
1 (AR)	68269695AB	PAD KIT, Front Disc Brake, Includes Hardware ONLY Sales Code BRD

REPAIR PROCEDURE:

Replace the front brake pads and hardware with the NEW revised front brake pad kit. Refer to the detailed service procedures available in DealerCONNECT> TechCONNECT under: Service Info> 05 - Brakes, Base> Hydraulic/Mechanical> PADS, Brake, Front> Removal/Installation.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
05-70-22-9K	Pads, Disc Brake - Replace Front Set (2 - Skilled)	4 - Chassis Systems	0.7 Hrs.

FAILURE CODE:

ZZ Service Action	1//
-------------------	-----