



NUMBER: 06-005-07

GROUP: Clutch

DATE: October 31, 2007

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of Chrysler LLC.

SUBJECT:

Clutch Pedal Squeak

OVERVIEW:

This bulletin involves lubricating the clutch return spring.

MODELS:

2007 - 2008	(JS41)	Avenger / Sebring
2007 - 2008	(PM)	Caliber
2007 - 2008	(MK49)	Compass
2007 - 2008	(MK74)	Patriot

NOTE: This information applies to models equipped with a T-355 or BG6 Manual Transmission (Sales Code DD7 or DEF) built prior to August 6, 2007 (MDH0806XX).

SYMPTOM/CONDITION:

A squeak sound may be heard when applying or releasing the clutch pedal.

DIAGNOSIS:

If the customer describes a squeak sound when applying the clutch pedal, perform the Repair Procedure

PARTS REQUIRED:

Qty.	Part No.	Description
1	04318066AB	Grease, Spray Lithium 1 can will service 30 vehicles

REPAIR PROCEDURE:

1. Using grease pn 04318066AB, lubricate the clutch return spring
2. Verify the squeak is eliminated.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Amount
06-45-01-93	Return Spring, Clutch - Lubricate (B)	0.2

FAILURE CODE:

ZZ	Service Action
----	----------------