



**NUMBER:** 08-069-15

**GROUP:** Electrical

**DATE:** July 15, 2015

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*

**THIS SERVICE BULLETIN IS ALSO BEING RELEASED AS RAPID RESPONSE TRANSMITTAL (RRT) 15-076. ALL APPLICABLE SOLD AND UN-SOLD RRT VIN'S HAVE BEEN LOADED. TO VERIFY THAT THIS RRT SERVICE ACTION IS APPLICABLE TO THE VEHICLE, USE VIP OR PERFORM A VIN SEARCH IN TECHCONNECT. ALL REPAIRS ARE REIMBURSABLE WITHIN THE PROVISIONS OF WARRANTY.**

**SUBJECT:**

Fuse Location Incorrectly Labeled

**OVERVIEW:**

This bulletin involves installing a sticker for the correct fuse locations on the front Power Distribution Center (PDC) cover.

**MODELS:**

2015 (LX) Chrysler 300

**NOTE: This bulletin applies to vehicles built on or after November 17, 2014 (MDH 1117XX) and on or before March 17, 2015 (MDH 0317XX).**

**SYMPTOM/CONDITION:**

The fuse locations don't match the layout according to the front PDC cover.

**DIAGNOSIS:**

If a customer's VIN is listed in VIP or your RRT VIN list, perform the repair. For all other customers that describe the symptom/condition listed above, perform the Repair Procedure.

**PARTS REQUIRED:**

Qty.	Part No.	Description
1	68294252AA	Power Distribution Center Label

**REPAIR PROCEDURE:**

1. Clean the surface of the front PDC cover and remove any dirt or residue.
2. Install the new fuse label sticker over the existing label on the inside of the front PDC cover.

**POLICY:**

Reimbursable within the provisions of the warranty.

***TIME ALLOWANCE:***

<b>Labor Operation No:</b>	<b>Description</b>	<b>Skill Category</b>	<b>Amount</b>
23-01-05-94	Label, PDC Fuse Cover - Install (1 - Semi-Skilled)	6 - Electrical and Body Systems	0.2 Hrs.

***FAILURE CODE:***

ZZ	Service Action
----	----------------