



To All Lamborghini Dealers and Licensed Service Point  
From Customer Service Department  
Subject Service campaign - Clamp for Misfire Pressure Sensor  
Group 140.1.31.00.05.ClampMisfirePressureSensor.GB  
Date 21.07.2005  
Pages 4

Automobili  
Lamborghini  
S.p.A.

### **Subject**

Clamps for misfire pressure sensors (p/n 07L906261)

### **Model / VIN-Range**

Gallardo models until VIN ZHWG\_11\_\_5LA02586

### **Information to the field**

In case you have a vehicle in the workshop Lamborghini recommends adding clamps to the misfire pressure sensors.

This modification must be performed on all cars involved at the next service.

Lamborghini recommends you to carry out this upgrade aiming to extend the life of these components.

### **Field solution**

Add a clamp in the misfire pressure sensors.

### **Spare Parts**

2 clamps – p/n 400251189B – available at the Lamborghini warehouse.



## Warranty Claim dates

This can be found on Lamborghini Web Portal in the Warranty section “Available campaigns”.

Campaign Code:	L140-A.04.05
Campaign Description:	Clamp for misfire pressure sensors
Cost Code:	50
Component Code:	CCA0405
Trouble Code:	220
Labour code:	CCA0405100
Labour Time:	1 h

Your Area Manager is at your full disposal for further information.

Best regards

Product Service


## Necessary material

2 clamps – p/n 400251189B


## Description of operations

**1.1** Adopt all precautions to prevent car damages and to work safe.

**1.2** Remove both misfire pressure sensors (see pictures below)



**1.3** Insert the clamps in the pipes where indicated in the picture below.



**1.4** Now you can assemble the two sensors back.