



To All Lamborghini Dealers and Licensed Service Point  
From Customer Service Department  
Subject Service campaign - New Routing for Gallardo E-Gear hydraulic pipes  
Group 140.3.01.00.05  
Date 18.07.2005  
Pages 4

Automobili  
Lamborghini S.p.A.

### **Subject**

New routing for the Gallardo E-Gear hydraulic pipes

### **Model / VIN-Range**

Only Gallardo E-Gear models until VIN ZHWG\_11S\_5LA02466

### **Information to the field**

In case you have a vehicle in the workshop Lamborghini recommends changing the routing of the Gallardo E-Gear Hydraulic pipes.

This modification must be performed on all cars involved at the next service.

Lamborghini recommends carrying out this upgrade aiming to extend the life of these components.

### **Field solution**

Routing and clamping of the E-Gear hydraulic pipes

### **Parts**

2 Clamps - p/n 400971850B - available at the Lamborghini warehouse

1-4

---

*The information and procedures published below are strictly confidential and intended exclusively for authorized operators and individuals. All copyrights are the property of Automobili Lamborghini S.p.A based on copyright law. The company reserves the right to make updates and modifications. The reprinting, reproduction, forwarding to unauthorized people and/or to third parties and partial or entire translation thereof are prohibited without written authorization from Automobili Lamborghini S.p.A.*

Via Modena,12  
I-40019 Sant'Agata  
Bolognese  
Tel +39 051 6817 652  
Fax +39 051-6817 709



## Warranty Claim data

This can be found on Lamborghini Web Portal in the Warranty section “Available campaigns”.

Campaign Code:	L140-A01.05
Campaign Description:	New routing for E-gear hydraulic pipes
Cost Code:	50
Component Code:	CCA0105
Trouble Code:	220
Labour Code:	CCA0105100
Labour Time:	0.25 h

Your Area Manager is at your full disposal for further information.

Best regards

Product Service



## Necessary material

2 Clamps - p/n 400971850B



## Description of operations

1.1 Adopt all precautions to prevent car damages and to work safe.

1.2 You will need to replace the old clamps with new clamps.

1.3 Picture number 3 indicates the first clamp to be replaced




Picture 3

*The information and procedures published below are strictly confidential and intended exclusively for authorized operators and individuals. All copyrights are the property of Automobili Lamborghini S.p.A based on copyright law. The company reserves the right to make updates and modifications. The reprinting, reproduction, forwarding to unauthorized people and/or to third parties and partial or entire translation thereof are prohibited without written authorization from Automobili Lamborghini S.p.A.*



1.4 Picture 4 indicates the 2<sup>nd</sup> clamp to be replaced.



Picture 4