



To All Lamborghini Dealers and Licensed Service Point
From Customer Service Department
Subject Correct positioning of wirings in contact with engine bay
heat protection grid
Group 147.09.00
Attachments -
Date 16.01.2006
Pages 2

Automobili
Lamborghini
S.p.A.

Subject

Correct positioning of the wiring in contact with engine bay heat protection grid.

Model / VIN-Range

Murciélago coupè (L147) models until VIN 1781

Information to the field

In case you have one of the involved cars in your workshop for a service or a PDI inspection, Lamborghini recommends checking the position of the wiring in contact with the heat protection grid of the engine bay (see attached pictures).

In case the wiring is not correctly positioned, please re-position it similar to shown in the attached pictures, in order to avoid wiring damage due to a in-correct contact with the protection grid.

Your Area Manager is at your full disposal for further information.

Best regards

Customer Service

1-2



Via Modena,12
I-40019 Sant'Agata
Bolognese
Tel +39 051 6817 652
Fax +39 051-6817 709



Description of operations

- 1.1 Adopt all precautions to prevent damage to the car and to work safe.
- 1.2 Check the position of the wiring in the contact point with the heat protection grid in the engine bay.

The pictures below show the possible position you may find.



- 1.3 If the wiring is not correctly positioned (Pic.2), re-position the wiring under the heat protection grid similar to shown in Pic.1.