

**MANUAL TRANSMISSION - ENGINE OIL MINDER - OIL CHANGE NOW  
INDICATOR MESSAGE INOPERATIVE - BUILT ON OR BEFORE 6/1/2015**

**TSB 15-0132**

**FORD:**

2014-2015 Fiesta

**ISSUE**

Some 2014-2015 Fiesta vehicles equipped with a manual transmission and built on or before 6/1/2015 may exhibit an oil change now indicator message that is inoperative.

**ACTION**

Reprogram the instrument panel cluster (IPC) and the powertrain control module (PCM) to the latest calibration using IDS version 96.04 or higher. Make sure you are connected to the internet when entering module programming to obtain the latest updates. Calibration files may also be obtained at [www.motorcraftservice.com](http://www.motorcraftservice.com).

<b>OPERATION</b>	<b>DESCRIPTION</b>	<b>TIME</b>
150132A	2014-2015 Fiesta With Manual Transmission: Reprogram The IPC And PCM (Do Not Use With Any Other Labor Operations)	0.4 Hr.

**WARRANTY STATUS:**

Eligible Under Provisions Of New Vehicle Limited Warranty Coverage

Warranty/ESP coverage limits/policies/prior approvals are not altered by a TSB. Warranty/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

**DEALER CODING**

<b>BASIC PART NO.</b>	<b>CONDITION CODE</b>
10849	04

NOTE: The information contained in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.