

**ATTENTION:**  
 GENERAL MANAGER ☐  
 PARTS MANAGER ☐  
 CLAIMS PERSONNEL ☐  
 SERVICE MANAGER ☐

IMPORTANT - All Service Personnel Should Read and Initial in the boxes provided, right.

|  |  |  |
|--|--|--|
|  |  |  |
|  |  |  |

© 2015 Subaru of America, Inc. All rights reserved.



QUALITY DRIVEN® SERVICE

## SERVICE BULLETIN

**APPLICABILITY:** 2013-2015MY BRZ  
 2006-2007MY B9 Tribeca

**NUMBER:** 18-178-15

**DATE:** 03/02/15

**SUBJECT:** Service Manual Corrections

### INTRODUCTION

The purpose of this bulletin is to provide a description of current changes to Service Manuals available via the Subaru Technical Information System (STIS) web site. The tables contained within this bulletin are to be used as guides for becoming aware of the latest changes. We advise you to always refer to the STIS web site when looking for the latest Service information. Printed pages will **not** be made available to update printed Service Manuals.

**Paper manuals may have different page numbering then what is reflected below, based on multiple new and revised pages. Please refer to the information contained on the STIS web site for all future, update service manual information.**

| YEAR | MODEL | SECTION                | PAGE(S)                 | DESCRIPTION OF CHANGE  |
|------|-------|------------------------|-------------------------|--|
| 2015 | BRZ   | Engine Mechanical      | EM-109-112              | Cylinder Block inspection steps changed/updated.                                     |
|      |       | Door Lock              | DL-97                   | Keyless ID registration steps changed/updated.                                       |
| 2014 | BRZ   | Summary                | IN-12,13                | Some Camshaft and valve specifications changed.                                      |
|      |       | Engine Control         | ES-82-89                | Diagnostic steps added for DTCs P0000A,000C, 0011,0021.                              |
|      |       |                        | ES-375                  | Diagnostic steps changed/updated for DTCs P0851, 852.                                |
|      |       | Engine Mechanical      | EM-35,49,50,56,80,82,84 | Camshaft and valve inspection and specifications changed/updated.                    |
|      |       |                        | EM-109-112              | Cylinder Block inspection steps changed/updated.                                     |
|      |       | Fuel                   | FU-77-80                | Fuel Filler Pipe exploded view, removal, installation and inspection has been added. |
|      |       | Automatic Transmission | AT-263                  | No. 4 brake clutch pack clearance adjustment changed.                                |
|      |       |                        | AT-308                  | Vent tube installation steps changed.  |
|      |       | Door Lock              | DL-97                   | Keyless ID registration steps changed/updated.                                       |

*Continued...*

| YEAR | MODEL      | SECTION                | PAGE(S)         | DESCRIPTION OF CHANGE  |
|------|------------|------------------------|-----------------|--|
| 2013 | BRZ        | Engine Control         | ES-82-89        | Diagnostic steps added for DTCs P0000A,000C, 0011,0021.                              |
|      |            |                        | ES-377          | Diagnostic steps changed/updated for DTCs P0851, 852.                                |
|      |            | Engine Mechanical      | EM-109-112      | Cylinder Block inspection steps changed/updated.                                     |
|      |            | Fuel                   | FU-74-77        | Fuel Filler Pipe exploded view, removal, installation and inspection has been added. |
|      |            | Automatic Transmission | AT-261          | No. 4 brake clutch pack clearance adjustment changed.                                |
|      |            |                        | AT-303          | Vent tube installation steps changed.  |
|      |            | Door Lock              | DL-97           | Keyless ID registration steps changed/updated.                                       |
|      |            | Outer Mirror           | MX-6            | Disassembly steps changed.   |
| 2007 | B9 Tribeca | Transmission           | 5AT(diag)-91    | Diagnostic steps for DTC P0882 changed/updated.                                      |
|      |            | Body                   | LAN(diag)-80    | Diagnostic steps for DTC U1321 changed/updated.                                      |
| 2006 | B9 Tribeca | Transmission           | 5AT(diag)-95    | Diagnostic steps for DTC P0882 changed/updated.                                      |
|      |            | Body                   | LAN(diag)-72-74 | Diagnostic steps for DTC U1321 changed/updated.                                      |