

- ATTENTION:**
- GENERAL MANAGER
 - PARTS MANAGER
 - CLAIMS PERSONNEL
 - SERVICE MANAGER

IMPORTANT - All Service Personnel Should Read and Initial in the boxes provided, right.

© 2015 Subaru of America, Inc. All rights reserved.



QUALITY DRIVEN® SERVICE

SERVICE BULLETIN

APPLICABILITY: 2008MY Forester
2011-2015MY Forester

NUMBER: 18-180-15
DATE: 04/01/15

SUBJECT: Service Manual Corrections

INTRODUCTION

The purpose of this bulletin is to provide a description of current changes to Service Manuals available via the Subaru Technical Information System (STIS) web site. The tables contained within this bulletin are to be used as guides for becoming aware of the latest changes. We advise you to always refer to the STIS web site when looking for the latest Service information. Printed pages will **not** be made available to update printed Service Manuals.

Paper manuals may have different page numbering then what is reflected below, based on multiple new and revised pages. Please refer to the information contained on the STIS web site for all future, update service manual information.

YEAR	MODEL	SECTION	PAGE(S)	DESCRIPTION OF CHANGE
2015	Legacy and Outback	Engine 1	EC(H4DO)-9,12,16,19,54-57	Emission Controls quick connect connectors removal, assembly and tips have been chaged/updated.
		Engine 2	EC(H6DO)-5,8,12,15,32-35	Emission Controls quick connect connectors removal, assembly and tips have been chaged/updated.
		Chassis	VDC(diag)-45,46,96-99	Diagnostic steps changed for DTC C1242, 1956, 1957.
		Body	WW-4,22,23,25,26	Washer Fluid Level Sensor removal, diagnosis and images have been added.
			INF(diag)-27-29	Diagnostic steps changed for DTC B224A.
			PRG(diag) 23,24,26,27,29,30,48,49	Diagnostic steps changed/added for DTC B250B, B250F, B2511
		KPS (diag) 62,67,68,70,74,76,80,81,83,85,87,89,91,93,94	Diagnostic steps changed/updated for DTC's B2779, 2785, 2786, 2789, B278A, 2793, B27A1, B27A2, B27A5, B27A6, B27A7, B27A8.	
2008	Legacy and Outback	Engine 2	EN(H4DOTC)(diag)-351	Diagnostic steps changed for DTC P2432.
2007	Legacy and Outback	Engine 2	EN(H4DOTC)(diag)-359	Diagnostic steps changed for DTC P2432.
2015	Forester	Transmission	CVT(diag) 56-58,62-64,133-136,138-141	Diagnostic steps changed/updated for DTC's P0716, P0720, P2747, P2751.
		Chassis	VDC(diag)-44,45	Diagnostic steps changed/updated for DTC C1242.
			BR-72	Brake Light Switch check steps changed/updated.
		Body	IDI(diag)-27,28	Diagnostic steps changed for DTC U1650.

Continued...

YEAR	MODEL	SECTION	PAGE(S)	DESCRIPTION OF CHANGE
2014	Forester	Transmission	CVT(diag)-48-50,53-55,94,101	Diagnostic steps changed/updated for DTC's P0716, P0720, P2747, P2751.
		Chassis	VDC(diag)-44,45	Diagnostic steps changed/updated for DTC C1242.
			BR-77	Brake Light Switch check steps changed/updated.
2015	Impreza	Chassis	BR-76	Brake Light Switch check steps changed/updated.
		Body	IDI(diag)-31,32	Diagnostic steps changed for DTC U1650.
2014	Impreza	Chassis	BR-74	Brake Light Switch adjustment and check steps changed/updated.
2013	Impreza	Chassis	BR-74	Brake Light Switch adjustment and check steps changed/updated.
2012	Impreza	Chassis	BR-72	Brake Light Switch adjustment and check steps changed/updated.
2015	WRX	Transmission	CVT (diag) 48-50,103-105,110-112,114-116	Diagnostic steps changed/updated for DTC's P0720, P1706, P2747, P2751.
		Chassis	VDC(diag)-49,50	Diagnostic steps changed/updated for DTC C1242.
		Body	IDI(diag)-27,28	Diagnostic steps changed for DTC U1650.