

- ATTENTION:**
 GENERAL MANAGER
 PARTS MANAGER
 CLAIMS PERSONNEL
 SERVICE MANAGER

IMPORTANT - All Service Personnel Should Read and Initial in the boxes provided, right.

© 2015 Subaru of America, Inc. All rights reserved.



QUALITY DRIVEN® SERVICE

SERVICE BULLETIN

APPLICABILITY: 2008-2015MY Impreza and XV Crosstrek
 2016MY Legacy and Outback
 2008-2016MY WRX and WRX STI

NUMBER: 18-183-15
DATE: 11/04/15

SUBJECT: Service Manual Corrections

INTRODUCTION

The purpose of this bulletin is to provide a description of current changes to Service Manuals available via the Subaru Technical Information System (STIS) web site. The tables contained within this bulletin are to be used as guides for becoming aware of the latest changes. We advise you to always refer to the STIS web site when looking for the latest Service information. Printed pages will **not** be made available to update printed Service Manuals.

Paper manuals may have different page numbering then what is reflected below, based on multiple new and revised pages. Please refer to the information contained on the STIS web site for all future, update service manual information.

YEAR	MODEL	SECTION	PAGES	DECIPTION OF CHANGE
2016	Legacy & Outback	Wiring Diagram	WI-26,40,53,67	Diagrams changed.
		Chassis	BR-74-79	Stop Light Switch servicing steps changed.
2015	Impreza	Wiring System	WI(HEV)-23,32	Diagrams changed.
		Chassis	BR-72-77	Stop Light Switch servicing steps changed.
2014	Impreza	Wiring System	WI(HEV)-22,31,49	Diagrams changed.
2013	Impreza	Chassis	BR-73-76	Stop Light Switch servicing steps changed.
2012	Impreza	Chassis	BR-70-74	Stop Light Switch servicing steps changed.
2011	Impreza	Chassis	BR-44-49	Stop Light Switch servicing steps changed.
2010	Impreza	Chassis	BR-44-49	Stop Light Switch servicing steps changed.
2009	Impreza	Chassis	BR-44-49	Stop Light Switch servicing steps changed.
2008	Impreza	Chassis	BR-45-50	Stop Light Switch servicing steps changed.
2016	WRX/STI	Transmission	CS-5	Diagrams changed.
2014	WRX/STI	Chassis	BR-49-54	Stop Light Switch servicing steps changed.

Continued...

YEAR	MODEL	SECTION	PAGES	DESCRIPTION OF CHANGE
2013	WRX/STI	Chassis	BR-47-52	Stop Light Switch servicing steps changed.
2012	WRX/STI	Chassis	BR-46-51	Stop Light Switch servicing steps changed.
2011	WRX/STI	Chassis	BR-48-53	Stop Light Switch servicing steps changed.
2010	WRX/STI	Chassis	BR-36-39	Stop Light Switch servicing steps changed.
2009	WRX/STI	Chassis	BR-36-39	Stop Light Switch servicing steps changed.
2008	WRX/STI	Chassis	BR-36-39	Stop Light Switch servicing steps changed.