
ATTENTION:

GENERAL MANAGER
PARTS MANAGER
CLAIMS PERSONNEL
SERVICE MANAGER

IMPORTANT - All Service Personnel Should Read and Initial in the boxes provided, right.



© 2015 Subaru of America, Inc. All rights reserved.



SERVICE BULLETIN

APPLICABILITY: 2013, 2015-16MY Legacy and Outback

2014-15MY Forester

SUBJECT: Service Manual Corrections

NUMBER: 18-184-15 **DATE:** 12/16/15

INTRODUCTION

The purpose of this bulletin is to provide a description of current changes to Service Manuals available via the Subaru Technical Information System (STIS) web site. The tables contained within this bulletin are to be used as guides for becoming aware of the latest changes. We advise you to always refer to the STIS web site when looking for the latest Service information. Printed pages will **not** be made available to update printed Service Manuals.

Paper manuals may have different page numbering then what is reflected below, based on multiple new and revised pages. Please refer to the information contained on the STIS web site for all future, update service manual information.

YEAR	MODEL	SECTION	PAGES	DECRIPTION OF CHANGE
2016	Legacy & Outback	Body	AC(diag)-11	Diagnostic steps updated.
			LAN(diag)-40	CAN Communication Circuit Check steps updated.
			LAN(diag)-88,89,91	LAN DTC check sheet changed.
2015	Legacy & Outback	Engine 1	FU(H4D0)-19,20,32,33	Illustrations changed.
			EC(H4D0)-2,27,28,45	Illustration changes and Torque specifications added.
			EN(H4D0)(diag)- 87,91,253,269,271, 273, 275 & 281	Wiring diagrams changed.
		Engine 2	CO(H6DO)-8	Wiring diagram changed.
			EN(H6DO)(diag)- 92,95,306,313,315, 317, 319 & 325	Wiring diagrams changed.
		Chassis	VDC(diag)-20,49,54,61,63,88	Wiring diagrams changed.
			PS(diag)-12,30	Wiring diagrams changed.
		Body	AC(diag)-11	Diagnostic steps updated.
			PSM(diag)-9,24	Wiring diagrams changed.
			PRG(diag)-38	Wiring diagram changed.
			LAN(diag)-36	CAN Communication Circuit Check steps updated.
			LAN(diag)-81,82,84	LAN DTC check sheet changed.
			BC(diag)-54	Wiring diagram changed.
2013	Legacy & Outback	Engine 1	FU(H4D0)-54	Crankshaft Sensor testing updated.
2015	Forester	Body	KPS(diag)-52,54	Diagnostic steps changed.
2014	Forester	Body	KPS(diag)-47,49	Diagnostic steps changed.

Bulletin Number: 18-184-15; Date: 12/16/15