		-				
The	purp	ose d	of tl	his bu	lletin	is to
avai	lable	via	the	Suba	ru Teo	chnica

al Information System (STIS) web site. The tables contained within this bulletin are to be used as guides for becoming aware of the latest changes. We advise you to always refer to the STIS web site when looking for the latest Service information. Printed pages will not be made available to update printed Service Manuals.

Paper manuals may have different page numbering then what is reflected below, based on multiple new and revised pages. Please refer to the information contained on the STIS web site for all future, update service manual information.

YEAR	MODEL	SECTION	PAGE	DESCRIPTION OF CHANGE			
Paper manuals may have different page numbering then what is reflected below, based on multiple new and revised pages. Please							
refer to th	refer to the information contained on the STI web site for all future, update service manual information.						
2016	Legacy & Outback	Engine 1	EN(H4D0)(diag)-275, 278,282,284	DTC Component Descriptions changed.			
		Engine 2	EN(H6D0)(diag)-306,375	Diagnostic steps changed.			
		Transmission	CVT(diag)-126-133	Diagnostic steps changed.			
		Body	AC(diag)-11	Diagnostic steps changed.			
			AB-26,27,29,31	Inspections changed.			
			GW-45-47	Windshield installation steps changed.			
			PRG-2,9,10	New illustration and caution changes.			
			PRG(diag)-57,58	Diagnostic steps added.			
			LAN(diag)-40	Diagnostic steps changed.			
			LAN(diag)-88,89,91	LAN DTC check sheet changed.			
			ES-28-30	Camera adjustments and error list added.			
2015	Legacy & Outback		FU(H4D0)-19,20,32,33	Intake Manifold images and steps changed.			
			EC(H4D0)-2,27,28,45	New and updated images and steps for EGR service.			
			EN(H4DO)(diag)- 87,91,226,253,269, 271,273,275,281	Diagnostic steps changed.			
			EN(H4DO)(diag)-93,95,97,99	DTC Component Descriptions changed.			
		Engine 2	CO(H6DO)-8	Radiator Fan diagram changed.			
			EN(H6D0)(diag)- 92,95,280,306,313, 315,317,319,325	Diagnostic steps changed.			

SUBJECT: Service Manual Corrections

INTRODUCTION provide a description of current changes to Service Manuals

2010-16MY Legacy and Outback

2013-14MY Tribeca

2012-16MY Impreza 2012-16MY WRX&STI 2012-16MY Forester 2013-16MY BRZ



QUALITY DRIVEN® SERVICE

18-185-16

03/10/16

NUMBER:

DATE:

SERVICE BULLETIN

Initial in the boxes CLAIMS PERSONNEL provided, right. SERVICE MANAGER © 2016 Subaru of America. Inc. All rights reserved.

IMPORTANT - AII

Service Personnel Should Read and

ATTENTION:

GENERAL MANAGER

APPLICABILITY:

PARTS MANAGER

YEAR	MODEL	SECTION	PAGE	DESCRIPTION OF CHANGE	
		Transmission	CVT(diag)-104-110	Diagnostic steps changed.	
		Ohaasia	VDC(diag)-20,49,54,61,63,88	Diagnostic steps changed.	
		Chassis	PS(diag)-12,30	Diagnostic steps changed.	
			AC(diag)-16	Diagnostic steps changed.	
			AB-23-25,27,29	Inspections changed.	
0045			PSM(diag)-9,24	Diagnostic steps changed.	
2015 (cont.)	Legacy & Outback	Body	PRG-2,9,10	New illustration and caution changes.	
	Ouldack		PRG(diag)-38,55	Diagnostic steps changed and added.	
			IM(diag)-37	Diagnostic steps changed.	
			LAN(diag)-36	Diagnostic steps changed.	
			LAN(diag)-81,82,84	LAN DTC check sheet changed.	
			ES-27-29	Diagnostic steps changed and added.	
			BC(diag)-54	Diagnostic steps changed.	
		Engine 1	EN(H4DO)(diag)-206	Diagnostic steps changed.	
2014	Legacy & Outback	Engine 2	EN(H6D0)(diag)-259,261,263	Diagnostic steps changed.	
	Outback	Body	AB-26,27,29,31	Inspections changed.	
		Engine 1	EN(H4DO)(diag)-208	Diagnostic steps changed.	
2013	Legacy & Outback	Engine 2	EN(H6D0)(diag)-260,262,264	Diagnostic steps changed.	
	Outback	Body	AB-30-32,35	Inspections changed.	
2012	Legacy & Outback	Body	AB-29,-31,35	Inspections changed.	
2011	Legacy & Outback	Body	AB-28-30,33	Inspections changed.	
2010	Legacy & Outback	Body	AB-26,27,30	Inspections changed.	
2014	Tribeca	Engine	EN(H6D0)(diag)- 244,246,248	Diagnostic steps changed.	
2013	Tribeca	Engine	EN(H6D0)(diag)- 245,248,249	Diagnostic steps changed.	
	Impreza -	Engine 1	EN(H4DO w/o HEV)(diag)- 332	Diagnostic steps changed.	
2016		Body	AB-30,31,33,37	Inspections changed.	
		Douy	ES-28-30	Diagnostic steps changed and added.	
	Impreza		Engine 1	EN(H4DO w/o HEV)(diag)- 231	Diagnostic steps changed.
2015		Engine 2	EN(H4DO HEV)(diag)-231	Diagnostic steps changed.	
		Desta	AB-24,25,27,31	Inspections changed.	
		Body	ES-28-30	Diagnostic steps changed and added.	
0014	Impreza -	Engine 1	EN(H4DO HEV)(diag)-240	Diagnostic steps changed.	
2014		Body	AB-33,34,36,40	Inspections changed.	
0010	Impreza -	Engine 1	EN(H4DO HEV)(diag)-203	Diagnostic steps changed.	
2013		Body	AB-34,37,40	Inspections changed.	
2012	Impreza -	Engine 1	EN(H4DO HEV)(diag)-194	Diagnostic steps changed.	
		Body	AB-32,34,38	Inspections changed.	
	- WRX & STI	Engine 1	EN(STI)(diag)-243,245,247	Diagnostic steps changed.	
2016		Engine 2	EN(w/o STI)(diag)-280	Diagnostic steps changed.	
		Body	AB-26,27,29,31	Inspections changed.	
			ES-20,27,29-32	Diagnostic steps changed and added.	

YEAR	MODEL	SECTION	PAGE	DESCRIPTION OF CHANGE	
2015		Engine 1	EN(STI)(diag)-229,231,233	Diagnostic steps changed.	
	WRX & STI	Engine 2	EN(w/o STI)(diag)-280	Diagnostic steps changed.	
		Body	AB-26,27,29,31	Inspections changed.	
2014	WRX & STI	Engine 1	EN(H4DOTC)(diag)- 248,250,252	Diagnostic steps changed.	
2013	WRX & STI	Engine 1	EN(H4DOTC)(diag)- 246,248,250	Diagnostic steps changed.	
2012	WRX & STI	Engine 1	EN(H4DOTC)(diag)- 236,238,240	Diagnostic steps changed.	
		Body & Electrical/ Wiring System	General Description	Illustration ch anged	
			Removal & Installation	Steps changed and added	
2016	Forestor	Transmission	General Description	Illustration changed	
2016	Forester	Diagnostics	DTC's B2282 & 2283	Diagnostic steps changed.	
			DTC P0451	Diagnostic steps changed.	
			DTC P0451	Diagnostic steps changed.	
		SRS Airbag System	Inspection after collision	Inspections changed.	
	Forester	Engine 1	EN(H4DO)(diag)-209	Diagnostic steps changed.	
2015		Body	AB-26,27,29,31	Inspections changed.	
2010			PRG-2,10,11,15,16	New illustration and caution changes.	
			KPS(diag)-52,54	Diagnostic steps changed.	
	Forester	Engine 1	EN(H4DO)(diag)-209	Diagnostic steps changed.	
2014		Body	AB-29,32,36	Inspections changed.	
2014			PRG-2,10,11,15,16	New illustration and caution changes.	
			KPS(diag)-47,49	Diagnostic steps changed.	
	Forester	Engine 1	EN(H4DO)(diag)-199	Diagnostic steps changed.	
2013		Engine 2	EN(H4DO)(diag)- 216,218,220	Diagnostic steps changed.	
2012	Forester	Engine 1	EN(H4DO)(diag)-199	Diagnostic steps changed.	
2016	BRZ	Manual Transmission	Removal	Steps changed.	
2015	BRZ	Manual Transmission	Removal	Steps changed.	
2014	BRZ	Manual Transmission	Removal	Steps changed.	
2013	BRZ	Manual Transmission	Removal	Steps changed.	

CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

SUBARU OF AMERICA, INC. IS ISO 14001 COMPLIANT

ISO 14001 is the international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.