
ATTENTION:

GENERAL MANAGER PARTS MANAGER CLAIMS PERSONNEL SERVICE MANAGER

IMPORTANT - All Service Personnel Should Read and Initial in the boxes provided, right.



© 2016 Subaru of America. Inc. All rights reserved.



SERVICE BULLETIN

APPLICABILITY: 2014-2016MY Forester

2007-2009MY Legacy/Outback

2016MY Crosstrek Hybrid

SUBJECT: Service Manual Corrections

NUMBER: 18-187-16

DATE: 06/02/16

INTRODUCTION

The purpose of this bulletin is to provide a description of current changes to Service Manuals available via the Subaru Technical Information System (STIS) web site. The tables contained within this bulletin are to be used as guides for becoming aware of the latest changes. We advise you to always refer to the STIS web site when looking for the latest Service information. Printed pages will **not** be made available to update printed Service Manuals.

Paper manuals may have different page numbering then what is reflected below, based on multiple new and revised pages. Please refer to the information contained on the STIS web site for all future, update service manual information.

YEAR	MODEL	SECTION	PAGE	DESCRIPTION OF CHANGE
2009	Legacy & Outback	Wiring System	WI-134	Wiring diagram changed.
2008	Legacy & Outback	Wiring System	WI-164	Wiring diagram changed.
2007	Legacy & Outback	Wiring System	WI-135	Wiring diagram changed.
2016	Forester	Diagnosis	DTC B1760	Diagnostic steps changed for DTC B1760.
2015	Forester	Body	OD(diag)-22	Diagnostic steps changed for DTC B1760.
2014	Forester	Body	OD(diag)-22	Diagnostic steps changed for DTC B1760.
2016	Crosstrek Hybrid	Body 2	HEV(diag)-32	Drive Cycle chart changed.
			HEV(diag)-71	Work Support added.
			HEV(diag)-153	Diagnostic steps changed for DTC P1C10.

Bulletin Number: 18-187-16; Date: 06/02/16