ATTENTION:

GENERAL MANAGER PARTS MANAGER CLAIMS PERSONNEL SERVICE MANAGER IMPORTANT - AII Service Personnel Should Read and Initial in the boxes provided, right.





SERVICE BULLETIN

2012 & 2015-2017MY Legacy/Outback APPLICABILITY:

2016-2017MY Forester

Service Manual Corrections SUBJECT:

NUMBER: 18-189-17

> DATE: 01/10/17

INTRODUCTION

The purpose of this bulletin is to provide a description of current changes to Service Manuals available via the Subaru Technical Information System (STIS) web site. The tables contained within this bulletin are to be used as guides for becoming aware of the latest changes. We advise you to always refer to the STIS web site when looking for the latest Service information. Printed pages will **not** be made available to update printed Service Manuals.

Paper manuals may have different page numbering then what is reflected below, based on multiple new and revised pages. Please refer to the information contained on the STIS web site for all future, update service manual information.

YEAR	MODEL	SECTION	PAGE	DESCRIPTION OF CHANGE
2017	Legacy/ Outback	Wiring System	WI-310-313	Power Window diagram changed.
			WI-353	Sunroof diagram changed.
2016	Legacy/ Outback	Body	EB-64	Rear Gate clearance adjustments changed.
		Wiring System	WI-308-311	Power Window diagram changed.
			WI-348	Sunroof diagram changed.
2015	Legacy/ Outback	Body	EB-65	Rear Gate clearance adjustments changed.
		Wiring System	WI-373-376	Power Window diagram changed.
			WI-446	Sunroof diagram changed.
2012	Legacy/ Outback	Transmission	CVT(diag)-86	Diagnostic steps changed for DTC P2764.
2017	Forester	Diagnostics	Diagnostic procedure for DTC P013A.	Diagnostic steps for DTC P013A changed.
		Body&Electrical Wiring System	Power Window System	Power Window diagram changed.
2016	Forester	Diagnostic	Diagnostic Procedure for DTC B2A06	Diagnostic steps for DTC P2A06 changed.

Bulletin Number: 18-189-17; Date: 01/10/17