



**NUMBER:** 24-007-15

**GROUP:** Heating & Air  
Conditioning

**DATE:** November 07, 2015

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*

**HELP USING THE wiTECH DIAGNOSTIC APPLICATION FOR FLASHING AN ECU IS AVAILABLE BY SELECTING “HELP” THEN “HELP CONTENTS” AT THE TOP OF THE wiTECH DIAGNOSTIC APPLICATION WINDOW.**

**THE wiTECH SOFTWARE IS REQUIRED TO BE AT THE LATEST RELEASE BEFORE PERFORMING THIS PROCEDURE.**

***SUBJECT:***

Air Conditioning Inoperative

***OVERVIEW:***

This bulletin involves replacing the Manual Climate Control Module.

***MODELS:***

2016	(FB)	Fiat 500X
2015	(BU)	Jeep Renegade

**NOTE: This bulletin applies to vehicles within the following markets/countries:  
NAFTA, EMEA.**

**NOTE: This bulletin applies to vehicles built on or before June 17, 2015 (MDH  
0617XX).**

***SYMPTOM/CONDITION:***

A small number of customers may experience the loss of air conditioning operation (AC will not turn on).

***DIAGNOSIS:***

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in TechCONNECT, verify all systems are functioning as designed. If DTCs or symptom conditions, are present other than the symptom condition listed above, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If the customer describes the symptom/condition listed above, perform the Repair Procedure.

**PARTS REQUIRED:**

Qty.	Part No.	Description
1	6CY57LXHAA	Climate Control Module (FB)
1	6CY58LXHAA	Climate Control Module (BU)

**REPAIR PROCEDURE:**

1. Replace the Manual Climate Control Module. Refer to the detailed service procedures available in DealerCONNECT> TechCONNECT under: Service Info> 24 - Heating and air Conditioning > Controls > CONTROL, A/C and Heater > Removal and Installation.
2. Clear all DTCs that may have been set in any module due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow them to be cleared.

**POLICY:**

Reimbursable within the provisions of the warranty.

**TIME ALLOWANCE:**

Labor Operation No:	Description	Skill Category	Amount
24-50-10-9B	Module, Heating Ventilation Air Conditioning (HVAC) - Replace (2 - Skill Level)	07 - A/C and Heating	0.4 Hrs

**FAILURE CODE:**

ZZ	Service Action
----	----------------