



Applies To: **2003 Element with M/T** – From VIN 5J6YH1...3L000001 thru 5J6YH1...3L009732 **October 11, 2011**

## 2003 Element: MIL Comes On With DTC P0420

(Supersedes 03-031, dated July 23, 2011, to revise the information marked by the black bars)

### REVISION SUMMARY

Under WARRANTY CLAIM INFORMATION, a flat rate time was changed.

### SYMPTOM

The MIL is on and DTC P0420 (catalyst system efficiency below threshold) is set.

### PROBABLE CAUSE

Specific driving conditions may cause the ECM/PCM to incorrectly interpret sensor inputs, setting DTC P0420.

### CORRECTIVE ACTION

Update the ECM/PCM software.

### WARRANTY CLAIM INFORMATION

The normal warranty applies.

OP#	Description	FR T
123503	Retrieve the DTC and clear codes with the HDS	0.3
125517	Update the ECM/PCM software	0.3

Failed Part: P/N 37820-PZD-A02

Defect Code: 072

Contention Code: B03

Skill Level: Repair Technician

### REPAIR PROCEDURE

1. Use the HDS to clear DTC P0420.
2. Make sure you have the *IN* CD (June '03 or later) loaded into your *IN* master terminal. If not, load the CD using the instructions that come with it.
3. Update the ECM/PCM software (refer to S/B 01-023, *Updating Control Units/Modules*).