

Applies To: **1999-04 Odyssey** – ALL**2003-04 Pilot** – ALL**2005 Pilot** – From VIN 5FNYP...5B000001 thru 5FNYP...5B053700**2005 Pilot** – From VIN 2HKYF...5H500001 thru 2HKYF...5H566360**February 9, 2007**

## Front Stabilizer Link Clunks

(Supersedes 07-001, dated January 20, 2007, to update the information marked with the black bars)

### PROBLEM

There is a clunk coming from the front stabilizer link(s).

### CORRECTIVE ACTION

Replace **both** front stabilizer links with updated parts.

### PARTS INFORMATION

Front Stabilizer Link Set (includes both links and new self-locking nuts):

P/N 06513-S0X-A00, H/C 8591513

### WARRANTY CLAIM INFORMATION

**In warranty:** The normal warranty applies.

Operation Number: 4161C7

Flat Rate Time: 0.5 hour

Failed Part: P/N 51320-S0X-C01  
H/C 7966096

Defect Code: 00504

Symptom Code: 04201

Template ID: 07-001A

Skill Level: Repair Technician

**Out of warranty:** Any repair performed after warranty expiration may be eligible for goodwill consideration by the District Parts and Service Manager or your Zone Office. You must request consideration, and get a decision, before starting work.

### REPAIR PROCEDURE

Replace both front stabilizer links:

- Refer to the Suspension section of the appropriate service manual, or
- Online, enter keyword **SUSP**, and select the appropriate repair procedure from the list:

Odyssey: **Damper/Spring Replacement**Pilot: **Front Stabilizer Link Removal/Installation**