

Customer Address

Throttle body ECU
Your Lamborghini Gallardo with chassis number:
S. Agata Bolognese, 07.25.2008

Dear Sir or Madam,

As a result of the continuous product monitoring, Automobili Lamborghini S.p.A. has found that the throttle body Electronic Control Unit (ECU) on certain vehicles could cause a decrease in engine power, reducing vehicle speed to about 35 mph (60 km/h) and reducing comfort.

In order to guarantee the proper engine functioning, it is therefore necessary to check and replace the throttle body ECU. Your vehicle is one of the vehicles affected.

We therefore kindly ask you to make your vehicle available to an Authorized Lamborghini Dealer for a maximum of 2 hours so that we can carry out the necessary checks and repairs. This work will, of course, be carried out at no charge to you.

Please contact an authorized Lamborghini Dealer or Service Point without delay to make an appointment. Please bring this letter and your Service Booklet with you when you visit the dealer, so that we can make all necessary entries.

If you have any queries regarding this measure please contact:

Automobili Lamborghini America, LLC

Tel: +1(248) 754-6088

Also your Lamborghini Dealer or Service Point is available to assist you.

We are sure you appreciate the need for this precautionary measure, and regret any inconvenience caused by this extra workshop visit.

Your co-operation will be appreciated.

Yours sincerely,

Automobili Lamborghini S.p.A.

S. Cieri
(Proxy holder)

M. Reggiani
(Head of Research & Development)

Automobili Lamborghini S.p.A.

Customer Service and Spare Parts

Fax: + 39 051 6817 709

Vehicle chassis No.:

Vehicle cannot be checked because it has been

- scrapped**
- stolen**
- sold to a domestic buyer**
- sold to an overseas buyer**

to new address:

Name: _____ **First name:** _____

Street: _____ **House No.:** _____

Post code: _____ **Town:** _____

Country: _____

Date / signature: