

To All Lamborghini Dealers and Licensed Service Point

From Customer Service Department

Subject Chain Tensioner Torque.

Group 1.03.00 Date 22/12/2011

Pages 5

Subject

Chain tensioner torque.

Model

Aventador LP700 MY 2012 From VIN CLA0091 to VIN CLA00188.

<u>Warning:</u> some vehicles included in this VIN range may not be affected, so check carefully on the Lamborghini WEB Portal (at the section named VIN Info) if the cars in your workshop or in your eventual stock are effectively affected before performing any other operation.

Information to the field

As a continuous product monitoring, Automobili Lamborghini Spa has found that on some vehicle an incorrect torque may be applied to the chain tensioner sporadically causing a seepage.

Field solution

Retightened the chain tensioner with an increased torque

The information and procedures published below are strictly confidential and intended exclusively for authorized operators and individuals. All copyrights are the property of Automobili Lamborghini S.p.A based on copyright law. The company reserves the right to make updates and modifications. The reprinting, reproduction, forwarding to unauthorized people and/or to third parties and partial or entire translation thereof are prohibited without written authorization from Automobili Lamborghini S.p.A.



Warranty Claim data

The warranty reimbursement request for this rework action will be managed by the following standard Warranty Claim procedures.

Campaign Code: L834-A.05.11

Campaign Description: Chain tensioner torque

Cost Code: 50

Component Code: CCA0511

Trouble Code: 220

Labour Code: CCA0511100

Labour Time: 0,4 h

Remember to fill all data in the section "Service and Recall Campaign" in the Warranty booklet of the vehicle as shown below.

Service/Service Recall/Rannel	Service/Service Richiamo/Rückruf
Servicio Llamada a Taller	Service/Service Recall/Rappel Servicio Llamada a Taller
Numero/Nummer Number/Numéro Número	Numero/Numero Number/Numéro Número
Data/Datum/Date/Date/Fecha	Data/Datum/Date/Date/Fecha
Deta riparazione/Reparaturidatum Repair Data/Date de reparation (15) vien vy	Data rioarazione/Reparaturdatum Repair Data/Date de réparation Fecha reparación
Firma / Unterschrift / Signature / Signature / Firma	Effectué par le concessionnaire / Éfectuado por el Concesionario Firma / Uniterschrift / Signature / Signature / Firma
Service/Service Service/Service Service/Service Recall/Rappel Llamada e Taller	Service/Service Service/Service Service/Service Llamada Taller
Numero/Nummer Number/Numero Numero	Numer o/Nummer Number Numer of
	Data/Datum/Date/Date/Fecha
Deta/Datum/Date/Pacha dd men yy	dd dim Vy

The information and procedures published below are strictly confidential and intended exclusively for authorized operators and individuals. All copyrights are the property of Automobili Lamborghini S.p.A based on copyright law. The company reserves the right to make updates and modifications. The reprinting, reproduction, forwarding to unauthorized people and/or to third parties and partial or entire translation thereof are prohibited without written authorization from Automobili Lamborghini S.p.A.





Operation description


1	Operation to be performed at cold engine.	
2	Place the car on a suitable lift in order to work safe from risks.	
3	Remove the rear central panel of the vehicle flat bottom (082503).	


The information and procedures published below are strictly confidential and intended exclusively for authorized operators and individuals. All copyrights are the property of Automobili Lamborghini S.p.A based on copyright law. The company reserves the right to make updates and modifications. The reprinting, reproduction, forwarding to unauthorized people and/or to third parties and partial or entire translation thereof are prohibited without written authorization from Automobili Lamborghini S.p.A.












The information and procedures published below are strictly confidential and intended exclusively for authorized operators and individuals. All copyrights are the property of Automobili Lamborghini S.p.A based on copyright law. The company reserves the right to make updates and modifications. The reprinting, reproduction, forwarding to unauthorized people and/or to third parties and partial or entire translation thereof are prohibited without written authorization from Automobili Lamborghini S.p.A.



_

Check with a torque wrench that the value applied to the chain tensioner bolt is equal to **55Nm**, in case is lower tighten it under specification.

Prescribed torque: 55Nm.



Reassembly

1 Refit the rear central portion of the vehicle flat bottom (082505).

Your Area Manager is at full disposal for further information.

Best regards

Customer Service

The information and procedures published below are strictly confidential and intended exclusively for authorized operators and individuals. All copyrights are the property of Automobili Lamborghini S.p.A based on copyright law. The company reserves the right to make updates and modifications. The reprinting, reproduction, forwarding to unauthorized people and/or to third parties and partial or entire translation thereof are prohibited without written authorization from Automobili Lamborghini S.p.A.