



SERVICE MANUAL BULLETIN

This Service Manual Bulletin is prepared by the Publications Department of New Flyer Industries Canada ULC. Refer to details below.

SMB-144

ISSUE DATE: Apr 24 2015

APPLICABILITY					
VEHICLE LENGTH	<input type="checkbox"/> 30ft.	<input type="checkbox"/> 35ft.	<input type="checkbox"/> 40ft.	<input type="checkbox"/> 60ft.	<input checked="" type="checkbox"/> ALL
VEHICLE TYPE	<input type="checkbox"/> High Floor	<input checked="" type="checkbox"/> Low Floor	<input type="checkbox"/> Invero®	<input type="checkbox"/> Xcelsior®	<input type="checkbox"/> ALL
FUEL TYPE	<input type="checkbox"/> Diesel	<input type="checkbox"/> Electric	<input type="checkbox"/> CNG	<input type="checkbox"/> LNG	<input checked="" type="checkbox"/> ALL
	<input type="checkbox"/> Diesel/Electric	<input type="checkbox"/> Gas/Electric	<input type="checkbox"/> Fuel Cell		
SUBJECT	Front Axle King Pin Replacement MAN V8-65L				
SECTION TITLE	1 - FRONT AXLE & SUSPENSION				
DETAILS	<p>This bulletin provides revised OEM information on the procedure for the installation of the MAN axle king pin.</p> <p>DO NOT apply grease to the king pin prior to inserting into needle bearing end of the steering knuckle.</p> <p>This information supersedes any prior information on this subject already provided in your New Flyer Service Manuals and is in SMB-069. Make this Service Bulletin available to service personnel to inform them of changed information.</p>				