



Service Bulletin

PRELIMINARY INFORMATION

Subject: Radio Display May Momentarily Flicker When Vehicle Is First Started Or While Driving

Models: 2015 Chevrolet Suburban, Silverado, Tahoe
2015 GMC Sierra, Yukon models

This PI was superseded to update Condition Concern. Please discard PIT5378A

Condition/Concern

Some customers may comment that the radio display flickers momentarily when first starting the vehicle or while driving

Recommendation/Instructions

Engineering is currently evaluating this concern. Please do not make any repairs or replace any parts.

Customer Information

Please communicate to the customer that we apologize for this inconvenience and that General Motors is currently evaluating this concern. This PI will be updated with additional details as they become available

Additional SI Keywords

Flash, Roll, overlap,

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION