



# Service Bulletin

## PRELIMINARY INFORMATION

**Subject:** Chime Volume Too Loud

**Models:** 2014-2015 Chevrolet Silverado  
2014-2015 GMC Sierra  
Equipped with RPO UQ3

*This PI was superseded to update Recommendation/Instructions. Please discard PIT5328A.*

### Condition/Concern

Some customers may comment that the chime volume is too loud.

### Recommendation/Instructions

Please reprogram the radio using the latest calibrations in TIS-2-WEB.

### Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
2810335	Radio Reprogramming with SPS	Use Published Labor Operation Time

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION