



# Service Bulletin


## TECHNICAL

**Subject:** Rear Vision Camera Brightness Adjustment

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Verano, Encore	2013	2016				

<b>Condition</b>	Some customers may comment that the rear vision camera image is dark.
<b>Cause</b>	This condition may be caused by the BRIGHTNESS level not set to the correct level.
<b>Additional Options</b>	RPO UVC

### Correction



While viewing the rear vision camera image, Press the MENU button to adjust brightness. **Do not** replace the rear vision camera for this issue. For further information on brightness control, refer to the Driver Assistance Systems in the Owners Manual.

If further diagnostics is required, refer to *Rear Vision Camera System Malfunction* in SI.

Provide the customer with this bulletin information for their records and future needs.

<b>Version</b>	1
<b>Modified</b>	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION