



Service Bulletin

PRELIMINARY INFORMATION

Subject: Radio Display May Momentarily Flicker When Vehicle Is First Started

Models: 2015 Chevrolet Silverado 1500
2015 Chevrolet Silverado 2500/3500, Suburban, Tahoe (with RPO AVF)
2015 GMC Sierra 1500
2015 GMC Sierra 2500/3500, Yukon models (with RPO AVF)
Equipped with RPO U42

Condition/Concern

Some customers may comment that the radio display flickers momentarily when first starting the vehicle.

Recommendation/Instructions

Engineering is currently evaluating this concern. Please do not make any repairs or replace any parts.

Customer Information

Please communicate to the customer that we apologize for this inconvenience and that General Motors is currently evaluating this concern. This PI will be updated with additional details as they become available.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION