



NUMBER: 23-004-15

GROUP: Body

DATE: February 07, 2015

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

THIS SERVICE BULLETIN IS ALSO BEING RELEASED AS RAPID RESPONSE TRANSMITTAL (RRT) 15-014. ALL APPLICABLE SOLD AND UN-SOLD RRT VIN'S HAVE BEEN LOADED. TO VERIFY THAT THIS RRT SERVICE ACTION IS APPLICABLE TO THE VEHICLE, USE VIP OR PERFORM A VIN SEARCH IN TECHCONNECT. ALL REPAIRS ARE REIMBURSABLE WITHIN THE PROVISIONS OF WARRANTY.

SUBJECT:

Side Steps Are Missing

OVERVIEW:

This bulletin involves inspecting for and if necessary installing the Side Steps.

MODELS:

2015 JK Jeep Wrangler

NOTE: This bulletin applies to vehicles built on or before January 9, 2015 (MDH 0109XX) equipped with Wrangler X Package (Sales Code AEB).

SYMPTOM/CONDITION:

Side Steps are missing. Inspect for and if necessary install the Side Steps.

DIAGNOSIS:

If a customer's VIN is listed in VIP or your RRT VIN list, perform the repair. For all other customers that describe the symptom/condition listed above, perform the Repair Procedure.

PARTS REQUIRED:

Qty.	Part No.	Description
1	82210571AD	4 Doors Side Steps Kit
1	82210565AD	2 Doors Side Steps Kit

NOTE: Each Kit provides left and right Side Steps. Only one Kit has to be ordered to repair one vehicle.

REPAIR PROCEDURE:

1. Install the Sides Steps. Refer to the detailed service procedures available in DealerCONNECT> TechCONNECT under: Service Info> 23- Body> Exterior - Step, Side.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
23-09-01-91	Side Step - Inspect And Install Left And Right (0- Skilled)	6 - ELECTRICAL AND BODY SYSTEMS	0.3 Hrs.

FAILURE CODE:

ZZ	Service Action
----	----------------