



# Preliminary Information

## PIP5587 Normal Engine Air Leak Whistle Noise From The PCV

### Models

| Brand:    | Model:         | Model Years: | VIN: |     | Engine:           | Transmissions: |
|-----------|----------------|--------------|------|-----|-------------------|----------------|
|           |                |              | from | to  |                   |                |
| Chevrolet | Silverado 1500 | 2019         | All  | All | 5.3L 6.2L L84 L87 | All            |
| GMC       | Sierra 1500    | 2019         | All  | All | 5.3L 6.2L L84 L87 | All            |

|                                   |  |
|-----------------------------------|--|
| <b>Involved Region or Country</b> | <b>North America</b>   |
| <b>Condition</b>                  | A vehicle may come into the dealer with a lean running concern and/or air leak noise from the PCV. |
| <b>Cause</b>                      | <b>The air rush or whistling noise is caused by the fixed orifice PCV</b>                          |

### Correction:

Test show that the PCV pipe is not leaking and should not be replaced.

There is not a correction for this noise and should be considered to be normal.

Engineering is looking into a design change at this time.

### Version History

|          |                    |
|----------|--------------------|
| Version  | <b>1</b>           |
| Modified | 9/12/2018- Created |

