



Preliminary Information

PIT5636 SES MIL DTC P1005

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 1500 (New Model)	2019	All	All	LV3, L82, L84, L87	All
GMC	Sierra 1500 (New Model)	2019	All	All	LV3, L82, L84, L87	All

Involved Region or Country	North America
Condition	Some customers may comment on a SES MIL. When the vehicle is checked for DTCs, a P1005 will be set in the ECM.
Cause	Under Investigation

Correction:

If no issues are found after performing normal SI diagnostics, technicians are to clear the DTC and perform a road test. If the condition does not return, no further repairs should be made at this time. Do NOT replace the K111 Fuel Pump Driver Control Module as this will not correct the concern.

GM Engineering is working to root cause this issue and when a fix becomes available, this PI will be converted into a bulletin.

Version History

Version	1
Modified	10/12/2018 - Created on

