ATTENTION:


GENERAL MANAGER

PARTS MANAGER

CLAIMS PERSONNEL

SERVICE MANAGER

IMPORTANT - All Service Personnel Should Read and Initial in the boxes provided, right.



QUALITY DRIVEN® SERVICE

© 2019 Subaru of America, Inc. All rights reserved.

SERVICE BULLETIN

APPLICABILITY: 2015-18MY Legacy and Outback

NUMBER: 06-69-19R

SUBARU

SUBJECT: Rear ABS Wheel Speed Sensor- Design Change

DATE: 02/07/19

REVISED: 02/20/19

INTRODUCTION:

This bulletin announces a design change made to the rear ABS wheel speed sensor on the models listed above. The change involves the addition of an additional shielding cover to protect the harness from damage caused by road debris.


PRODUCTION CHANGE INFORMATION:

This bulletin will be revised with the starting VINs for this production change when they become available.

PART INFORMATION:

Description	Part Number	Application	
SENSOR ASSEMBLY- REAR RIGHT	27540AL10B	2015MY Outback	
	27540AL12B	2015-18MY Outback	
	27540AL08B	2015-2018MY Legacy	
SENSOR ASSEMBLY- REAR LEFT	27540AL11B	2015MY Outback	
	27540AL13B	2015-18MY Outback	
	27540AL09B	2015-18MY Legacy	

REMINDER: Always order the most up-to-date replacement parts based on the specific VIN being repaired.



CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

Subaru of America, Inc. is ISO 14001 Compliant

ISO 14001 is the international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.

Continued...

Bulletin Number: 06-69-19R; Revised: 02/20/19

SERVICE PROCEDURE / INFORMATION:

REMINDER: Customer satisfaction and retention starts with performing quality repairs.

The service procedures for diagnosis and replacement of the ABS wheel speed sensor assembly remain unchanged. Always refer to the applicable Service Manual and review the full requirements of the repair being performed. The Service Manual procedures contain information critical to performing an effective repair the first time and every time. This includes but is not limited to: important SAFETY precautions, proper inspection criteria, necessary special tools, required processes and related one-time-use parts needed for a complete and lasting repair.

WARRANTY / CLAIM INFORMATION:

For vehicles within the Basic New Car Limited Warranty period or covered by an active Subaru Added Security Classic or Gold plan, this repair may be submitted using the following claim information:

Labor Description	Labor Operation #	Labor Time	Fail Code
ABS WHEEL SPEED SENSOR R&R	B566-321	0.3	
EACH ADDITIONAL ABS WHEEL SPEED SENSOR R&R	C566-325	0.2	UJW-42
ABS / VDC SYSTEM TESTING & DIAGNOSIS	C566-300	0.5	

IMPORTANT REMINDERS:

- SOA strongly discourages the printing and/or local storage of service information as previously released information and electronic publications may be updated at any time.
- Always check for any open recalls or campaigns anytime a vehicle is in for servicing.
- Always refer to STIS for the latest service information before performing any repairs.

Bulletin Number: 06-69-19R; Revised: 02/20/19