



# Preliminary Information

## PIC4888A HHR-SS (Turbo) Problems with Dingy Towing

### Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	HHR SS	2008 - 2010	All	All	LNF	All

### Supersession Statement

This PI was superseded to update Model years. Please discard PIC4888.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition / Concern

**A customer might have inquiries about "dingy" towing the HHR-SS (Turbo) behind another vehicle. It should be noted, there have been field complaints that the normal dingy towing mounting hardware will NOT fit on this vehicle. This is due to interference between the dingy towing mounting hardware and the turbo intercooler.**

### Recommendations / Instructions

**This is considered normal operation/design and relocation of the turbo intercooler should NOT be attempted.**

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.



GENERAL MOTORS